




Pozitie	Cantitate	Numar tip	Denumire	PG
1	1	316063520	Armature compl.,230V	35
2	1	311009770	Field coil 230 V elec	33
3	1	344493180	Cable with plug	27
4	1	344097360	Cable sleeve	11
5	1	343362490	Cable clip	12
6	1	141117060	Self-tap. fill. h. screw	12
7	2	344498880	Strand compl.	11
8	1	315013660	Motor housing	22
9	1	343430940	Switch rod	11
10	1	343397810	Switch slide,H/L	11
11	1	143115690	Ball bearing,6x19x6	13
12	1	344097870	Rubber bushing	11
13	1	343436590	Baffle	13
15	1	343430910	2 part motor cap	20
16	3	141113180	Self-tap. fill. h. screw	11
17	4	141123490	Fillister head screw	11
18	1	143195470	O-ring	11
19	1	315202610	Bearing flange	28
20	1	344160400	Open-end spanner	16
22	1	344099150	Handle	19
23	1	316051720	Spindle head compl.	47
24	1	343082710	Electronic unit,230V	31
25	1	343409640	Switch	19
26	2	316046890	Brush holder compl. cut out,230V	22
27	1	316046900	Carbon brush set cut-off	22
28	1	399999990	Part not needed	
30	1	316063500	Gear parts compl.	20
31	1	630820000	Collet 6mm with flange nut (double flat)	
35	1	338057510	Rating plate	11
36	1	399999990	Part not needed	
61	1	316065220	Spindle head compl.	33
62	1	143115930	Ball bearing,	19
63	1	143111090	Ball bearing, 10x30x9	24
64	1	141180370	Retaining ring	11
65	1	316080360	Planet carrier compl.	
66	1	341080230	Butting washer	11
68	3	143115450	3eedle roller and cage	16
69	1	143115490	Compensating washer	11
70	1	143115470	Compensating washer	11
71	1	316051700	Luefter mit Staubschutzkorb	17
75	1	316059800	Spindle lock	21
98	2	143195530	O-ring	11
880	1	344130920	Grease 100G	31
1001	1	338505710	Wiring diagram	

